

Contact: Brenda Flower

Tel: (705) 528-9979 Email: westwind@csolve.net www.westwindyachtscanada.com

Silverton 34 Convertible - 1985

12,500#

250 Gallons

34' 0"

6

\$37,000



Length Weight Fuel Sleeps Power

12'6 Beam Draft 3'1" Water

40 Gallons

Twin Crusaders 5.7L, 270hp each – direct drive inboards

Accommodations

V-Berth - large bed w/storage cupboard & shelves under Cockpit - with glass sliding door and screen to cabin Salon with pull-out sofa bed Lower helm removed Galley down with convertible dinette opposite Head with vanity and shower stall with door 3 Hatches with screens Opening portlights with screens

Galley

2 Burner alcohol/electric stove Microwave Toaster oven Kuerig coffee maker Fridge - 12v/110 Large stainless steel sink

Electronics

Standard depth sounder Standard speed indicator Compass Windlass control Remote controlled spotlight New Icom VHF - flybridge VHF in cabin

Equipment

Generator Heat/Air Windlass w/ dash control - chain & rode Ice maker installed in cabinet where lower helm removed Hardwood flooring throughout 4 Batteries (2 house, 1 start, 1 generator) Smart Charger Battery switch Manual head, vanity and shower stall with door Pressure hot & cold water system w/new supply hoses New hot water tank Shore water inlet Wash-down with hose in cockpit

Shore power w/2 cords Y-Plug Trim tabs Horns AM/FM radio Fume detector Marine BBQ mounted at transom Sun pad cushion Fender racks New custom swim platform All existing safety equipment All existing mooring equipment

Excluding: Dinghy and motor

This Silverton 34 has undergone a long list of recent upgrades, both esthetic and structural, with approximately \$50,000 invested in 2015. She is now ready for new owners and fitted-out for many more years of enjoyable, trouble-free cruising. See below for the complete list of upgrades.

Power Boat Guide says "Built on a solid fiberglass hull, the rakish styling of the 34 Silverton has held up well over the years. A single stateroom, galley-down floor plan that sleeps 6 in comfort with the convertible dinette, pull-out sofa and V-berth cabin."

The V-berth in this Silverton Convertible has been very tastefully customized with the bed filled in with cupboards added below for clothing storage. The cockpit with glass sliding door is a wonderful place to entertain and BBQ. You will enjoy the 360° view from the salon or the fly bridge which seats five. All the key equipment for comfortable cruising ... generator, air/heat, windlass, ice maker, BBQ and new custom swim platform with davit system!

All details are believed to be correct, but not guaranteed by owner or Broker. Some information may have been sourced from manufacturer's brochures. It is the Purchaser's responsibility to have all engines, systems and integrity of the vessel inspected. Page 1 of 2

2015 Reconditioning and Upgrades

Mechanical/Structural		
Stringers	Replaced inboard engine	
	stringers from transom to dinette,	
	including traverse frames and	
	tank beds.	
Engines	Tune-ups completed, added	
	intake strainers, replaced fuel fill	
	and cooling water hoses.	
	Replaced valve cover gaskets and	
	oil caps. Replaced original	
	exhaust system with new custom-	
	made mufflers and new exhaust	
	hoses.	
Generator	Overhauled valves and tuned up	
	ignition. New impellers, strainer,	
	intake and exhaust valves. Hoses	
	replaced to marine code	
	standards. Tap valve replaced	
	with lever operated ball valve.	
Water System	New hot water tank with ignition	
	protection and approved wiring.	
	New hot and cold water hoses,	
	clamps, valves, etc. to marine code standards.	
Head	New charcoal filter	
Thru Hulls	Replaced all above and below	
	through-hull fittings for galley	
	sink, head sink, bilge pumps, air	
	conditioner drain. New ball valve	
	for A/C unit. New forward bilge	
	pump, New wash-down pump	
	intake hose, all hoses and fittings	
	to current marine code standards.	
Fuel Senders	New starboard fuel sender, and	
	gaskets on both gages. Both	
	reading correctly.	
Batteries	New starter battery, 4 terminal	
	covers, ground cables for	
	batteries and motors, battery tie-	
	down straps. Wiring diagram	
	provided	
Wiring	Isolated AC from DC on electrical	
_	panel box. New wiring on bridge	
	to marine code standards	

Esthetic Repairs	
------------------	--

Exterior	New custom-built fiberglass 36"
	swim platform with dinghy davit
	system and swim ladder.
	New bow window cover (Sunbrella).
	Second opaque window cover
	repaired.
	Pulpit teak strips removed.
	Reinforced mounting and
	refinished with gel coat.
	New antifouling paint on hull.
	New Bruce anchor and windlass
	safety lock. New Danforth anchor
	and rope for stern. New tow rope.
	New port, starboard and transom
	ladder steps with anti-skid
	covering. New custom fit outdoor
	carpeting on deck.
Interior	Replaced cabin helm with ice
	maker.
	Reupholstered dinette seats with
	marine vinyl in neutral beige.
	New fitted custom sheets,
	comforter and memory foam in V-
	berth.
	New custom oak divider between
	galley and salon.
	New toaster oven and Kuerig coffee
	maker with refillable pods in galley.
	New up-scale scatter rugs

Totals

- Hindson Marina, Penetanguishene \$24,854.85
- O'Rourke Boat Repair (fiberglass) 21,325.00
- Dinette seat covering, v-berth linens,
- toaster oven, coffee maker and more 1,500.00
 Davit system with swim ladder 2,500.00

\$50,179.85